

ELECTRONIC TRANSMISSION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 7,892,469 B2 Confirmation No. : 3564
Inventors : Florencia Lim et al.
Issued : February 22, 2011
Art Unit : 1744
Examiner : Edmund H. Lee
Title : METHOD OF MAKING A NON-COMPLAINT BALLOON FOR A
CATHETER

Docket No.: : ACSC 68062
Customer No. : 24201

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:

The above-identified patent application file has been found to have the errors set forth in the enclosed Certificate of Correction. It is requested that a Certificate of Correction be issued and returned to us. Since the errors occurred in the final printing phase of the patent, no fee is enclosed. However, should the Office determine that a fee is required, please charge our Deposit Account No. 06-2425.

The errors are verifiable in the patent application file as follows:

ERROR

Drawing page, Sheet 3 of 3, delete current

VERIFICATION

PTO error. See Amendment dated 10/8/07 at

ERROR

page and insert instead replacement Sheet 3
of 3.
Column 11, line 13, after "300" insert --psi--.

VERIFICATION

page 2 with attachment.
PTO error. See application at page 25.

We respectfully request that the Certificate of Correction be expeditiously issued since the errors reported herein were incurred through the fault of the United States Patent and Trademark Office. This document is being transmitted electronically.

Attached hereto is Form PTO/SB/44 which is suitable for printing.

This document is being transmitted electronically.

Date: January 30, 2012

Respectfully submitted,

FULWIDER PATTON LLP

By: /Thomas H. Majcher/
Thomas H. Majcher, Registration No. 31,119

THM:he

FULWIDER PATTON LLP
Howard Hughes Center
6060 Center Drive, Tenth Floor
Los Angeles, CA 90045
Telephone: (310) 824-5555
Facsimile: (310) 824-9696
Customer No. 24201